








Поз. 1.1




Поз. 1.2




Поз. 2.1



Поз. 2.2




Поз. 3



Поз. 5

Поз.	Позначення	Найменування	Кільк.	Маса од., кг.	Примітка
Деталі:					
1.1		Кутик $\frac{60 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=800	1	3,54	
1.2		Кутик $\frac{60 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=800	1	3,54	
2.1		Кутик $\frac{60 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=450	1	1,98	
2.2		Кутик $\frac{60 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=450	1	1,98	
3		Кутик $\frac{60 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=550	2	2,37	
4		Кутик $\frac{45 \times 5 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=60	8	0,20	
5		Труба $\frac{100 \times 80 \text{ ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=1600	1	17	
8		Круг $\frac{\phi 16 \text{ С245 ДСТУ2251-93}}{\text{С245 ГОСТ27772-88}}$ L=400	1	0,25	
Стандартні вироби:					
6		Болт М16х35 ГОСТ 7798-70	4	0,11	
7		Болт М16х140 ГОСТ 7798-70	2	0,26	
8		Гайка М16 ГОСТ 5915-70	14	0,04	
9		Шайба 16 Гост 6958-78	16	0,01	
10		Шпилька М16х380 ГОСТ 22042-76	4	0,58	



Зварні шви варити електродом Е42 ГОСТ 9467-75, Висота шва 5 мм.

</								