








Поз.	Позначення	Найменування	Кільк.	Маса од., кг.	Примітка
Деталі:					
1		Швелер 6,5У 3436-96 L=700	2	3,62	
2		Куттик $\frac{45 \times 5}{C245}$ ДСТУ2251-93 ГОСТ27772-88 L=184	2	0,6	
3		Круг $\frac{\#16}{C245}$ ДСТУ2251-93 ГОСТ27772-88 L=1050	2	1,7	
4		Круг $\frac{\#10}{C245}$ ДСТУ2251-93 ГОСТ27772-88 L=400	1	0,25	
Стандартні вироби:					
5		Гайка М16 ГОСТ 5915-70	8	0,04	
6		Шайба 16 Гост 6958-78	8	0,01	



Зварні шви варити електродом Е42 ГОСТ 9467-75, Висота шва 5 мм.

</								